



1: Mkr (MHz)	2: Mkr (MHz)	dB
1: 19.0000	4.308	
2> 20.1000	1.167	
3: 21.5000	4.409	
4: 22.0000	5.982	

The sudden rise in VSWR at ~21MHz is because of the LO leakage at RF port.

[Receiver Considerations for Jupiter](#)

[Block Diagram of Receiver](#)

[Block Diagram with Specifications](#)